

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING







Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter

Division Director

1594 West North Temple, Suite 1210			
Box 145801	Partial: XXX	Complete:	Exploration:
Salt Lake City, Utah 84114-5801 Inspection	on Date & Time	: 7/8/98 / 8:0	0a.m1:30p.m.
(801) 538-5340			ection: <u>6/30/98</u>
(801) 359-3940 (Fax)	Daic	of Last Hispe	201011. <u>0/30/30</u>

Mine Name: <u>Crandall Canyon Mine</u> County: <u>Emery</u> Permit Number: <u>ACT/015/032</u>								
Permittee and/or Operator's Name: Genwal Resources, Inc.								
Business Address: P.O. Box 1420, Huntington, Utah 84528								
Type of Mining Activity: Underground XXX Surface Prep. Plant Other								
Company Official(s): Gary Gray								
State Officials(s): Stephen J. Demczak Federal Official(s): None								
Weather Conditions: Raining, Sunny, 80's								
Existing Acreage: Permitted-5049 Disturbed-10.20 Regraded5 Seeded5 Bonded-10.20								
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded								
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture								
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

<u>Instructions</u>

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<u>EVALUATED</u>	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS		Ц	ĹĬ	ĹÌ
3.	TOPSOIL	\Box	ĹĬ	Ĺ	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	Ш	[XX]	[XX]
b.	SEDIMENT PONDS AND IMPOUNDMENTS		ΞĪ		Ц
c.	OTHER SEDIMENT CONTROL MEASURES		Π	Π	ĹĬ
d.	WATER MONITORING		\Box	\Box	ĹÌ
e.	EFFLUENT LIMITATIONS	\Box	ĹÌ	ĹĬ	Ш
5.	EXPLOSIVES		\Box	ĹÌ	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	Ц	\Box	\Box	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	Ш	Ĺĺ	ĹÌ
8.	NONCOAL WASTE	\Box	\Box	\Box	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	\Box	\Box	\Box	\Box
10.	SLIDES AND OTHER DAMAGE	\coprod^{-1}	П	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	Ц	\Box	\Box
12.	BACKFILLING AND GRADING	[<u>X</u> X]	Ц	[XX]	[XX]
13.	REVEGETATION	Ц	\sqcup	\Box	\Box
14.	SUBSIDENCE CONTROL		\Box	\Box	\Box
15.	CESSATION OF OPERATIONS	\Box	\Box		\Box
16.	ROADS:				
	CONSTRUCTION/MAINTENANCE/SURFACING	Ц	\Box		\Box
b.	DRAINAGE CONTROLS	\Box	\Box	\Box	\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box		\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	Ц	\Box	\Box	\Box
19.	AVS CHECK (4th Quarter-April, May, June)(date)	\Box	\Box	\Box	\Box
20.	AIR QUALITY PERMIT	\Box	\Box	\Box	\Box
21.	BONDING & INSURANCE	ΓĪ	[]	[]	[]



INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 7/8/98

(Comments are Numbered to Correspond with Topics Listed Above)

DIVERSIONS -4a.

The undisturbed diversions above and next to the material storage area were not designed. This ditch has been riprapped. Therefore, a violation was written 98-39-3-1. The permittee must submit designs and get Division approval for the ditch. This ditch is to keep water off the pad area and put the water into to the bypass culvert which is under the mine pad.

12. **BACKFILLING AND GRADING -**

There is a cutslope located within the material storage area. This cut slope is not shown on the maps. The cutslope is 46 feet high and was caused by cutting in to the embankment an extra 10 feet during mine development of the pad area. Since it is not shown on the maps or addressed in the text, a violation was written 98-39-3-1. Failure to conduct mining as approved in the Mining and Reclamation Plan.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Gary Gray (Genwal) Given to: Joe Helfrich (DOGM)

Henry Austin (OSM)

Filed to: Price Field Office

Date: July 27, 1998

Inspector's Signature: